

EXHIBIT F-3

Attachment 3

OIS-OMT: [REDACTED]

Outage Dispatch Tool (Read Only)

Version 1.6 (3/30/2013)

| | | | | | | | |
|---------------------|----------------------------------|------------------------|---|------------------|--|---------------------|------------------------|
| OIS #: | 1404752 | Paradise (17) | 1st Call: | 14:48 07/14/2021 | Comments for Customers: Our preliminary determination is that your outage was caused by an equipment issue in your area. PG&E Personnel are investigating the cause. | | |
| Substation: | 10283 (PARADISE) | Addr.: | 13586 BADER MINE RD, PARADISE | | | | |
| Circuit: | 102831105 | SSD: | | | | | |
| Outage Dev.: | {1291} | Outage Remarks: | OR: N/A-15 MIN ETA [REDACTED] 15:20 07/14/2021 | | | | |
| Dev. Addr.: | 630° NE/O BADER MINE RD; 340° NW | Repair Time: | 04:00 Duration (HH MM) | | | | |
| Level: | DEVICE | Hazard: | Wire Down Outage | ETOR: | 23:59 07/14/2021 3 updates | Find / Reset | Verify |
| Customers: | 0 | IVR Cause: | REPAIR WIRE DWN | Clear | Restore | Print | Trouble Reports |
| Start Time: | 14:48 07/14/2021 | Access: | Available | Save | Affected Customers | Exit | Upgrade to xfmr |
| Complete: | 22:50 07/14/2021 | Assigned DO: | | Contact: | | | |

Crew Information

Repair Crew Requested: 17 00 07/14/2021

| Seq.# | Name | Type | Crew Size | Dispatch | Enroute | ETA | Onsite | Stop |
|-------|------------|--------|-----------|------------------|------------------|------------------|------------------|------------------|
| 1 | [REDACTED] | REPAIR | 3 | 17:10 07/14/2021 | 18:25 07/14/2021 | 20:00 07/14/2021 | 19:05 07/14/2021 | 22 56 07/14/2021 |
| 2P | [REDACTED] | T-MAN | 0 | 15:17 07/14/2021 | | | | 15:18 07/14/2021 |
| 3S | [REDACTED] | T-MAN | 0 | 14:51 07/14/2021 | 14:53 07/14/2021 | | 15:22 07/14/2021 | 17:10 07/14/2021 |

FAS Crew Comments

FAS Crew Comments (Outbound):

~LAT:LONG 39.79973:-121.58492 , FUSE 1291-120H TYPE ELF~

FAS Crew Comments (Inbound):

[REDACTED] (14-JUL-21 17:10)
WIRE DOWN, OAK TREE, CREW TO RPR WIRE DOWN

Material Information

| | | | | |
|----------------------|--------------------------|-------------------|--------------------------|---|
| Poles: | 0 | Pri Spans: | 75 | Quantity & Description (Pole type, X-ARM, Insulation, etc.): SAP 100400403 2 ACSR, SLEEVES 75 CONDUCTOR OH:2 ACSR:BROKEN/DAMAGED / REPLACE / PART SET 4 CONN/SPLICE OH:SLEEVE COMPRESSION ACSR:BURNT / REPLACE |
| Transformer: | 0 | Sec Spans: | 0 | |
| Service: | 0 | X-Arm: | 0 | |
| Joint Pole: | <input type="checkbox"/> | Tree Crew: | <input type="checkbox"/> | |
| Material List | | | | Personnel & Equipment (Flagman, CHP, Public works, Spill Kit, Boom Trk, etc.): SAP 100400403 Personnel Remarks: CREW 3 Setup Remarks: SMALL BUCKET OK, DIRT DRIVEWAY |